

Fleet #	Plant Model	Frame Hrs	Component	Last Overhaul Hrs	Last Overhaul Date	Current Comp Hours
DT29	Disposed	38,354	Engine	26,878	10-Jun-15	11,476
DT29	Disposed	38,354	Injectors	26,878	10-Jun-15	11,476
DT29	Disposed	38,354	LH Turbo	26,878	10-Jun-15	11,476
DT29	Disposed	38,354	RH Turbo	26,878	10-Jun-15	11,476
DT29	Disposed	38,354	LH Fuel Pump	36,215	24-Jan-18	2,139
DT29	Disposed	38,354	RH Fuel Pump	26,878	10-Jun-15	11,476
DT29	Disposed	38,354	Compressor (R)	37,808	28-Nov-18	546
DT29	Disposed	38,354	Compressor (F)	26,878	10-Jun-15	11,476
DT29	Disposed	38,354	Water Pump	36,980	03-May-18	1,374
DT29	Disposed	38,354	Radiator	21,399	08-Jul-11	16,955
DT29	Disposed	38,354	Engine Damper	26,878	10-Jun-15	11,476
DT29	Disposed	38,354	Transmission	37,482	12-Sep-18	872
DT29	Disposed	38,354	Transmission Cooler	21,399	08-Jul-11	16,955
DT29	Disposed	38,354	Transmission Pump	37,482	12-Sep-18	872
DT29	Disposed	38,354	Differential	28,317	03-Jul-13	10,037
DT29	Disposed	38,354	LH Final Drive	37,066	18-Jul-18	1,288
DT29	Disposed	38,354	RH Final Drive	37,066	18-Jul-18	1,288
DT29	Disposed	38,354	LHR Wheel Bgs (Pre-Load)	37,066	18-Jul-18	1,288
DT29	Disposed	38,354	RHR Wheel Bgs (Pre-Load)	37,066	18-Jul-18	1,288
DT29	Disposed	38,354	LHR Brakes	37,066	18-Jul-18	1,288
DT29	Disposed	38,354	RHR Brakes	37,066	18-Jul-18	1,288
DT29	Disposed	38,354	Brake Coolers	15,500	10-Jan-10	22,854
DT29	Disposed	38,354	LHR Strut		01-Sep-06	38,354
DT29	Disposed	38,354	RHR Strut		01-Sep-06	38,354
DT29	Disposed	38,354	LHF Strut	25,705	19-Sep-12	12,649
DT29	Disposed	38,354	RHF Strut		01-Sep-06	38,354
DT29	Disposed	38,354	LHF Wheel Bearings		01-Sep-06	38,354
DT29	Disposed	38,354	RHF Wheel Bearings		01-Sep-06	38,354
DT29	Disposed	38,354	LHR Wheel Bearings	37,066	18-Jul-18	1,288
DT29	Disposed	38,354	RHR Wheel Bearings	37,066	18-Jul-18	1,288
DT29	Disposed	38,354	LHF Brakes		01-Sep-06	38,354
DT29	Disposed	38,354	RHF Brakes		01-Sep-06	38,354
DT29	Disposed	38,354	LH Steering Cylinder	26,759	13-Dec-12	11,595
DT29	Disposed	38,354	RH Steering Cylinder	31,881	15-Jan-15	6,473
DT29	Disposed	38,354	LH Hoist Cylinder		01-Sep-06	38,354
DT29	Disposed	38,354	LH Lower Hoist Cylinder Pin	34,221	17-Mar-17	4,133
DT29	Disposed	38,354	RH Hoist Cylinder		01-Sep-06	38,354
DT29	Disposed	38,354	RH Lower Hoist Cylinder Pin	34,221	17-Mar-17	4,133
DT29	Disposed	38,354	Hoist-Steering Pump		01-Sep-06	38,354
DT29	Disposed	38,354	Brake Cooling Pump		01-Sep-06	38,354
DT29	Disposed	38,354	Orbital Steering Valve	29,023	18-Nov-13	9,331
DT29	Disposed	38,354	Operators Seat	37,066	18-Jul-18	1,288
DT29	Disposed	38,354	Frame		01-Sep-06	38,354
DT29	Disposed	785-5				
DT56	Disposed	43,998	Engine	22,075	20-Dec-12	21,923
DT56	Disposed	43,998	Injectors	22,075	20-Dec-12	21,923
DT56	Disposed	43,998	LH Turbo	22,075	20-Dec-12	21,923
DT56	Disposed	43,998	RH Turbo	40,730	01-May-18	3,268

DT56	Disposed	43,998	LH Fuel Pump	22,075	20-Dec-12	21,923
DT56	Disposed	43,998	RH Fuel Pump	22,075	20-Dec-12	21,923
DT56	Disposed	43,998	Compressor (R)	35,478	05-Apr-16	8,520
DT56	Disposed	43,998	Compressor (F)	22,075	20-Dec-12	21,923
DT56	Disposed	43,998	Water Pump	30,999	16-Dec-14	12,999
DT56	Disposed	43,998	Radiator	40,425	11-Mar-18	3,573
DT56	Disposed	43,998	Engine Damper	33,971	23-Aug-15	10,027
DT56	Disposed	43,998	Transmission	32,048	19-May-15	11,950
DT56	Disposed	43,998	Transmission Cooler	40,425	11-Mar-18	3,573
DT56	Disposed	43,998	Transmission Pump	32,048	19-May-15	11,950
DT56	Disposed	43,998	Differential	26,133	04-Dec-13	17,865
DT56	Disposed	43,998	LH Final Drive	26,133	04-Dec-13	17,865
DT56	Disposed	43,998	RH Final Drive	26,133	04-Dec-13	17,865
DT56	Disposed	43,998	LHR Wheel Bgs (Pre-Load)	26,133	04-Dec-13	17,865
DT56	Disposed	43,998	RHR Wheel Bgs (Pre-Load)	26,133	04-Dec-13	17,865
DT56	Disposed	43,998	LHR Brakes	26,133	04-Dec-13	17,865
DT56	Disposed	43,998	RHR Brakes	26,133	04-Dec-13	17,865
DT56	Disposed	43,998	Brake Coolers		15-Jun-06	43,998
DT56	Disposed	43,998	LHR Strut	38,554	22-Jan-17	5,444
DT56	Disposed	43,998	RHR Strut	39,021	15-Apr-17	4,977
DT56	Disposed	43,998	LHF Strut	40,412	09-Mar-18	3,586
DT56	Disposed	43,998	RHF Strut		15-Jun-06	43,998
DT56	Disposed	43,998	LHF Wheel Bearings		15-Jun-06	43,998
DT56	Disposed	43,998	RHF Wheel Bearings		15-Jun-06	43,998
DT56	Disposed	43,998	LHR Wheel Bearings	31,232	19-Jan-15	12,766
DT56	Disposed	43,998	RHR Wheel Bearings	31,232	19-Jan-15	12,766
DT56	Disposed	43,998	LHF Brakes		15-Jun-06	43,998
DT56	Disposed	43,998	RHF Brakes		15-Jun-06	43,998
DT56	Disposed	43,998	LH Steering Cylinder	26,410	02-Jan-14	17,588
DT56	Disposed	43,998	RH Steering Cylinder	22,635	05-Jun-14	21,363
DT56	Disposed	43,998	LH Hoist Cylinder	26,867	06-Feb-14	17,131
DT56	Disposed	43,998	LH Lower Hoist Cylinder Pin	26,125	02-Dec-13	17,873
DT56	Disposed	43,998	RH Hoist Cylinder	25,488	10-Oct-13	18,510
DT56	Disposed	43,998	RH Lower Hoist Cylinder Pin	31,243	21-Jan-15	12,755
DT56	Disposed	43,998	Hoist-Steering Pump	32,718	27-May-15	11,280
DT56	Disposed	43,998	Brake Cooling Pump		15-Jun-06	43,998
DT56	Disposed	43,998	Orbital Steering Valve	27,693	16-Jun-14	16,305
DT56	Disposed	43,998	Operators Seat	38,560	25-Jan-17	5,438
DT56	Disposed	43,998	Air Conditioning System		01-Jul-17	43,998
DT56	Disposed	43,998	Frame		15-Jun-06	43,998
DT56	Disposed	785-5				
DT113	Disposed	25,825	Engine	19,300	15-Mar-11	6,525
DT113	Disposed	25,825	Injectors	19,300	15-Mar-11	6,525
DT113	Disposed	25,825	LH Turbo	19,300	15-Mar-11	6,525
DT113	Disposed	25,825	RH Turbo	19,300	15-Mar-11	6,525
DT113	Disposed	25,825	LH Fuel Pump	19,300	15-Mar-11	6,525
DT113	Disposed	25,825	RH Fuel Pump	19,300	15-Mar-11	6,525
DT113	Disposed	25,825	Compressor (R)	19,300	15-Mar-11	6,525
DT113	Disposed	25,825	Compressor (F)	19,300	15-Mar-11	6,525
DT113	Disposed	25,825	Water Pump	19,300	15-Mar-11	6,525

DT113	Disposed	25,825	Radiator	24,995	31-May-18	830
DT113	Disposed	25,825	Engine Damper	19,300	15-Mar-11	6,525
DT113	Disposed	25,825	Transmission	24,995	31-May-18	830
DT113	Disposed	25,825	Transmission Cooler	24,995	31-May-18	830
DT113	Disposed	25,825	Transmission Pump	24,995	31-May-18	830
DT113	Disposed	25,825	Differential		15-Jun-01	25,825
DT113	Disposed	25,825	LH Final Drive		15-Jun-01	25,825
DT113	Disposed	25,825	RH Final Drive		15-Jun-01	25,825
DT113	Disposed	25,825	LHR Brakes	25,737	18-Nov-18	88
DT113	Disposed	25,825	RHR Brakes	25,737	18-Nov-18	88
DT113	Disposed	25,825	Brake Coolers		15-Jun-01	25,825
DT113	Disposed	25,825	LHR Strut	20,884	11-Jul-13	4,941
DT113	Disposed	25,825	RHR Strut	22,876	15-Sep-17	2,949
DT113	Disposed	25,825	LHF Strut	22,808	04-Sep-17	3,017
DT113	Disposed	25,825	RHF Strut	22,507	12-Aug-17	3,318
DT113	Disposed	25,825	LHF Wheel Bearings		15-Jun-01	25,825
DT113	Disposed	25,825	RHF Wheel Bearings		15-Jun-01	25,825
DT113	Disposed	25,825	LHR Wheel Bearings		15-Jun-01	25,825
DT113	Disposed	25,825	RHR Wheel Bearings		15-Jun-01	25,825
DT113	Disposed	25,825	LHF Brakes		15-Jun-01	25,825
DT113	Disposed	25,825	RHF Brakes		15-Jun-01	25,825
DT113	Disposed	25,825	LH Steering Cylinder	24,056	19-Dec-17	1,769
DT113	Disposed	25,825	RH Steering Cylinder	24,056	19-Dec-17	1,769
DT113	Disposed	25,825	LH Hoist Cylinder	25,484	02-Aug-18	341
DT113	Disposed	25,825	LH Lower Hoist Cylinder Pin		15-Jun-01	25,825
DT113	Disposed	25,825	RH Hoist Cylinder		15-Jun-01	25,825
DT113	Disposed	25,825	RH Lower Hoist Cylinder Pin		15-Jun-01	25,825
DT113	Disposed	25,825	Hoist-Steering Pump	22,140	27-Oct-16	3,685
DT113	Disposed	25,825	Brake Cooling Pump		15-Jun-01	25,825
DT113	Disposed	25,825	Orbital Steering Valve	22,140	27-Oct-16	3,685
DT113	Disposed	25,825	Operators Seat	20,990	25-Jul-13	4,835
DT113	Disposed	25,825	Air Conditioning System		01-Jul-17	25,825
DT113	Disposed	25,825	Frame		15-Jun-01	25,825

DT113 Disposed 785-5

Fleet #	Plant Model	Frame Hrs	Component	Last Overhaul Hrs	Last Overhaul Date	Hours to Overhaul
DT46	Disposed	36,168	Engine	17,597	13-Aug-32	2,429
DT46	Disposed	36,168	Injectors	17,597	15-Oct-09	2,429
DT46	Disposed	36,168	LH Turbo	17,597	15-Oct-09	2,429
DT46	Disposed	36,168	RH Turbo	17,597	15-Oct-09	2,429
DT46	Disposed	36,168	LH Fuel Pump	17,597	15-Oct-09	2,429
DT46	Disposed	36,168	RH Fuel Pump	17,597	15-Oct-09	2,429
DT46	Disposed	36,168	Compressor (R)	34,018	10-Feb-18	18,850
DT46	Disposed	36,168	Compressor (F)	34,018	10-Feb-18	18,850
DT46	Disposed	36,168	Water Pump	31,502	28-Jun-16	16,334
DT46	Disposed	36,168	Radiator	36,508	17-Dec-18	21,340
DT46	Disposed	36,168	Engine Damper	24,784	28-Jun-14	-1,384
DT46	Disposed	36,168	Transmission	16,999	15-Aug-09	-5,169
DT46	Disposed	36,168	Transmission Cooler	23,290	1-Apr-13	1,122

DT46	Disposed	36,168	Transmission Pump	16,999	15-Aug-09	-5,169
DT46	Disposed	36,168	Differential	35,272	28-Jul-18	17,104
DT46	Disposed	36,168	LH Final Drive	34,018	18-Feb-18	15,850
DT46	Disposed	36,168	RH Final Drive	34,018	18-Feb-18	15,850
DT46	Disposed	36,168	LHR Wheel Bgs (Pre-Load)	34,018	18-Feb-18	-150
DT46	Disposed	36,168	RHR Wheel Bgs (Pre-Load)	34,018	18-Feb-18	-150
DT46	Disposed	36,168	LHR Brakes	34,018	18-Feb-18	15,850
DT46	Disposed	36,168	RHR Brakes	34,018	18-Feb-18	15,850
DT46	Disposed	36,168	Brake Coolers		15-Jun-06	-18,168
DT46	Disposed	36,168	LHR Strut	33,669	28-Nov-17	18,501
DT46	Disposed	36,168	RHR Strut	33,669	28-Nov-17	18,501
DT46	Disposed	36,168	LHF Strut	30,451	28-Oct-15	15,283
DT46	Disposed	36,168	RHF Strut	24,483	10-Jun-14	9,315
DT46	Disposed	36,168	LHF Wheel Bearings		15-Jun-06	-12,168
DT46	Disposed	36,168	RHF Wheel Bearings		15-Jun-06	-12,168
DT46	Disposed	36,168	LHR Wheel Bearings	34,018	18-Feb-18	15,850
DT46	Disposed	36,168	RHR Wheel Bearings	34,018	18-Feb-18	15,850
DT46	Disposed	36,168	LHF Brakes	8,304	15-Jun-08	-7,864
DT46	Disposed	36,168	RHF Brakes	8,304	15-Jun-08	-7,864
DT46	Disposed	36,168	LH Steering Cylinder	26,126	24-Sep-14	10,958
DT46	Disposed	36,168	RH Steering Cylinder	21,010	24-Dec-11	5,842
DT46	Disposed	36,168	LH Hoist Cylinder	32,159	11-Nov-16	16,991
DT46	Disposed	36,168	LH Lower Hoist Cylinder Pin	28,347	19-Mar-15	16,179
DT46	Disposed	36,168	RH Hoist Cylinder	34,955	3-Jul-18	19,787
DT46	Disposed	36,168	RH Lower Hoist Cylinder Pin	28,347	19-Mar-15	16,179
DT46	Disposed	36,168	Hoist-Steering Pump	18,468	15-Aug-10	3,300
DT46	Disposed	36,168	Brake Cooling Pump	8,304	15-Jun-08	-6,864
DT46	Disposed	36,168	Orbital Steering Valve	20,925	4-Dec-11	5,757
DT46	Disposed	36,168	Operators Seat	33,730	5-Dec-17	7,562
DT46	Disposed	36,168	Air Conditioning System		1-Jul-17	-18,168
DT46	Disposed	36,168	Frame		15-Jun-06	3,832
DT46	Disposed	785-5				
DT55	Disposed	38,412	Engine	21,982	14-Apr-13	4,570
DT55	Disposed	38,412	Injectors	21,982	14-Apr-13	4,570
DT55	Disposed	38,412	LH Turbo	36,313	18-Mar-18	18,901
DT55	Disposed	38,412	RH Turbo	36,313	18-Mar-18	18,901
DT55	Disposed	38,412	LH Fuel Pump	21,982	14-Apr-13	4,570
DT55	Disposed	38,412	RH Fuel Pump	21,982	14-Apr-13	4,570
DT55	Disposed	38,412	Compressor (R)	21,982	14-Apr-13	4,570
DT55	Disposed	38,412	Compressor (F)	37,906	13-Jan-19	20,494
DT55	Disposed	38,412	Water Pump	34,430	4-Jul-16	17,018
DT55	Disposed	38,412	Radiator	30,830	3-Jul-15	13,418
DT55	Disposed	38,412	Engine Damper	34,190	11-Jun-16	5,778
DT55	Disposed	38,412	Transmission	31,734	28-Sep-15	7,322
DT55	Disposed	38,412	Transmission Cooler	30,830	3-Jul-15	6,418
DT55	Disposed	38,412	Transmission Pump	31,734	28-Sep-15	7,322
DT55	Disposed	38,412	Differential	29,541	9-Mar-15	9,129
DT55	Disposed	38,412	LH Final Drive	23,318	12-Aug-13	2,906

DT55	Disposed	38,412	RH Final Drive	23,318	12-Aug-13	2,906
DT55	Disposed	38,412	LHR Wheel Bgs (Pre-Load)	23,318	12-Aug-13	
DT55	Disposed	38,412	RHR Wheel Bgs (Pre-Load)	23,318	12-Aug-13	
DT55	Disposed	38,412	LHR Brakes	23,318	12-Aug-13	2,906
DT55	Disposed	38,412	RHR Brakes	23,318	12-Aug-13	2,906
DT55	Disposed	38,412	Brake Coolers		15-Jun-06	-20,412
DT55	Disposed	38,412	LHR Strut		15-Jun-06	-17,412
DT55	Disposed	38,412	RHR Strut		15-Jun-06	-17,412
DT55	Disposed	38,412	LHF Strut		15-Jun-06	-17,412
DT55	Disposed	38,412	RHF Strut		15-Jun-06	-17,412
DT55	Disposed	38,412	LHF Wheel Bearings	36,962	27-Sep-18	22,550
DT55	Disposed	38,412	RHF Wheel Bearings	21,982	14-Apr-13	7,570
DT55	Disposed	38,412	LHR Wheel Bearings	23,318	12-Aug-13	2,906
DT55	Disposed	38,412	RHR Wheel Bearings	23,318	12-Aug-13	2,906
DT55	Disposed	38,412	LHF Brakes		15-Jun-06	-18,412
DT55	Disposed	38,412	RHF Brakes		15-Jun-06	-18,412
DT55	Disposed	38,412	LH Steering Cylinder	32,844	25-Jan-16	15,432
DT55	Disposed	38,412	RH Steering Cylinder	19,198	19-Jun-12	1,786
DT55	Disposed	38,412	LH Hoist Cylinder	31,441	21-Aug-15	14,029
DT55	Disposed	38,412	LH Lower Hoist Cylinder Pin	24,469	7-Dec-13	10,057
DT55	Disposed	38,412	RH Hoist Cylinder	35,647	2-Nov-16	18,235
DT55	Disposed	38,412	RH Lower Hoist Cylinder Pin	24,469	7-Dec-13	10,057
DT55	Disposed	38,412	Hoist-Steering Pump	17,200	29-Jun-11	-212
DT55	Disposed	38,412	Brake Cooling Pump	17,200	29-Jun-11	-212
DT55	Disposed	38,412	Orbital Steering Valve	27,752	11-Sep-14	9,340
DT55	Disposed	38,412	Operators Seat	37,217	21-Oct-18	8,805
DT55	Disposed	38,412	Air Conditioning System		1-Jul-17	-20,412
DT55	Disposed	38,412	Frame		15-Jun-06	1,588

DT55	Disposed	785-5				
-------------	-----------------	--------------	--	--	--	--

Fleet #	Plant Model	Frame Hrs	Component	Last Overhaul Hrs	Last Overhaul Date	Current Comp Hours
WC13	Disposed	47,043	Engine	44,714	25-Dec-17	2,329
WC13	Disposed	47,043	Injectors	44,714	25-Dec-17	2,329
WC13	Disposed	47,043	LH Turbo	44,714	25-Dec-17	2,329
WC13	Disposed	47,043	RH Turbo	44,714	25-Dec-17	2,329
WC13	Disposed	47,043	LH Fuel Pump	44,714	25-Dec-17	2,329
WC13	Disposed	47,043	RH Fuel Pump	44,714	25-Dec-17	2,329
WC13	Disposed	47,043	Compressor (R)	44,714	25-Dec-17	2,329
WC13	Disposed	47,043	Compressor (F)	44,714	25-Dec-17	2,329
WC13	Disposed	47,043	Water Pump	44,714	25-Dec-17	2,329
WC13	Disposed	47,043	Radiator	44,714	25-Dec-17	2,329
WC13	Disposed	47,043	Engine Damper	44,714	25-Dec-17	2,329
WC13	Disposed	47,043	Transmission	39,108	9-Jun-16	7,935
WC13	Disposed	47,043	Transmission Cooler	39,108	9-Jun-16	7,935
WC13	Disposed	47,043	Transmission Pump	39,108	9-Jun-16	7,935
WC13	Disposed	47,043	Differential	18,524	15-Feb-11	28,519
WC13	Disposed	47,043	LH Final Drive	46,366	15-Sep-18	677

WC13	Disposed	47,043	RH Final Drive	46,366	15-Sep-18	677
WC13	Disposed	47,043	LH Rear Brakes	46,366	15-Sep-18	677
WC13	Disposed	47,043	RH Rear Brakes	46,366	15-Sep-18	677
WC13	Disposed	47,043	Brake Coolers	18,524	15-Feb-11	28,519
WC13	Disposed	47,043	LH Rear Strut	0	15-Jun-04	47,043
WC13	Disposed	47,043	RH Rear Strut	0	15-Jun-04	47,043
WC13	Disposed	47,043	LH Front Strut	28,829	28-Dec-13	18,214
WC13	Disposed	47,043	RH Front Strut	27,425	22-Sep-13	19,618
WC13	Disposed	47,043	LH Front Wheel Bearings	8,654	15-Jun-09	38,389
WC13	Disposed	47,043	RH Front Wheel Bearings	8,654	15-Jun-09	38,389
WC13	Disposed	47,043	LH Rear Wheel Bearings	46,366	15-Sep-18	677
WC13	Disposed	47,043	RH Rear Wheel Bearings	46,366	15-Sep-18	677
WC13	Disposed	47,043	LH Front Brakes	8,654	15-Jun-09	38,389
WC13	Disposed	47,043	RH Front Brakes	8,654	15-Jun-09	38,389
WC13	Disposed	47,043	LH Steering Cylinder	25,801	8-Apr-13	21,242
WC13	Disposed	47,043	RH Steering Cylinder	25,801	8-Apr-13	21,242
WC13	Disposed	47,043	LH Hoist Cylinder	25,801	8-Apr-13	21,242
WC13	Disposed	47,043	RH Hoist Cylinder	7,774	16-Aug-12	39,269
WC13	Disposed	47,043	Hoist-Steering Pump	0	15-Jun-04	47,043
WC13	Disposed	47,043	Brake Cooling Pump	0	15-Jun-04	47,043
WC13	Disposed	47,043	Orbital Steering Valve	44,714	15-Dec-17	2,329
WC13	Disposed	47,043	Operators Seat	32,244	25-Nov-14	14,799
WC13	Disposed	785-5				

Dump Truck Component Hours at 28 February '19

Fleet #	Plant Model	Frame Hrs	Component	Last Overhaul Hrs	Last Overhaul Date	Current Comp Hours	Scheduled Hrs	Hours to Overhaul
DT13	785-5	41,601	Engine	29,365	04-Jun-14	12,236	21,000	
DT13	785-5	41,601	Injectors	29,365	04-Jun-14	12,236	21,000	8,764
DT13	785-5	41,601	LH Turbo	29,365	04-Jun-14	12,236	21,000	8,764
DT13	785-5	41,601	RH Turbo	29,365	04-Jun-14	12,236	21,000	8,764
DT13	785-5	41,601	LH Fuel Pump	20,926	08-Aug-15	20,675	21,000	325
DT13	785-5	41,601	RH Fuel Pump	29,365	04-Jun-14	12,236	21,000	8,764
DT13	785-5	41,601	Compressor (R)	29,365	04-Jun-14	12,236	21,000	8,764
DT13	785-5	41,601	Compressor (F)	29,365	04-Jun-14	12,236	21,000	8,764
DT13	785-5	41,601	Water Pump	38,166	30-Apr-17	3,435	21,000	17,565
DT13	785-5	41,601	Radiator	21,274	10-Jun-11	20,327	21,000	673
DT13	785-5	41,601	Engine Damper	29,365	04-Jun-14	12,236	10,000	-2,236
DT13	785-5	41,601	Transmission	26,460	31-Aug-13	15,141	14,000	-1,141
DT13	785-5	41,601	Transmission Cooler	21,274	10-Jun-11	20,327	14,000	-6,327
DT13	785-5	41,601	Transmission Pump	26,460	31-Aug-13	15,141	14,000	-1,141
DT13	785-5	41,601	Differential	17,622	29-Nov-09	23,979	18,000	-5,979
DT13	785-5	41,601	LH Final Drive	41,493	08-Oct-18	108	18,000	17,892
DT13	785-5	41,601	RH Final Drive	41,493	08-Oct-18	108	18,000	17,892
DT13	785-5	41,601	LHR Brakes	41,493	08-Oct-18	108	18,000	17,892
DT13	785-5	41,601	RHR Brakes	41,493	08-Oct-18	108	18,000	17,892
DT13	785-5	41,601	Brake Coolers	17,622	29-Nov-09	23,979	18,000	-5,979
DT13	785-5	41,601	LHR Strut		15-Sep-04	41,601	21,000	-20,601
DT13	785-5	41,601	RHR Strut		15-Sep-04	41,601	21,000	-20,601
DT13	785-5	41,601	LHF Strut	27,045	05-Sep-13	14,556	21,000	6,444
DT13	785-5	41,601	RHF Strut	39,147	15-Nov-17	2,454	21,000	18,546
DT13	785-5	41,601	LHF Wheel Bearings	29,062	30-Dec-15	12,539	24,000	11,461
DT13	785-5	41,601	RHF Wheel Bearings	18,125	15-Feb-10	23,476	24,000	524
DT13	785-5	41,601	LHR Wheel Bearings	41,493	08-Oct-18	108	18,000	17,892
DT13	785-5	41,601	RHR Wheel Bearings	41,493	08-Oct-18	108	18,000	17,892
DT13	785-5	41,601	LHF Brakes	18,125	15-Feb-10	23,476	20,000	-3,476
DT13	785-5	41,601	RHF Brakes	18,125	15-Feb-10	23,476	20,000	-3,476
DT13	785-5	41,601	LH Steering Cylinder	39,762	27-Mar-18	1,839	21,000	19,161
DT13	785-5	41,601	RH Steering Cylinder	15,562	01-Jul-15	26,039	21,000	-5,039
DT13	785-5	41,601	LH Hoist Cylinder		15-Sep-04	41,601	21,000	-20,601
DT13	785-5	41,601	LH Lower Hoist Cylinder Pin	32,992	02-Oct-15	8,609	24,000	15,391
DT13	785-5	41,601	RH Hoist Cylinder	39,148	12-Nov-17	2,453	21,000	18,547
DT13	785-5	41,601	RH Lower Hoist Cylinder Pin	32,992	02-Oct-15	8,609	24,000	15,391
DT13	785-5	41,601	Hoist-Steering Pump	26,460	31-Aug-13	15,141	21,000	5,859
DT13	785-5	41,601	Brake Cooling Pump	17,622	29-Nov-09	23,979	21,000	-2,979
DT13	785-5	41,601	Orbital Steering Valve	39,263	07-Jan-18	2,338	21,000	18,662
DT13	785-5	41,601	Operators Seat	41,010	21-Jul-18	591	10,000	9,409
DT13	785-5	41,601	Frame		15-Sep-04	41,601	40,000	-1,601
DT13	785-5	Morowa						
DT15	785-5	39,271	Engine	24,375	31-Dec-09	14,896	21,000	6,104
DT15	785-5	39,271	Injectors	24,375	31-Dec-09	14,896	21,000	6,104
DT15	785-5	39,271	LH Turbo	24,375	31-Dec-09	14,896	21,000	6,104
DT15	785-5	39,271	RH Turbo	24,375	31-Dec-09	14,896	21,000	6,104
DT15	785-5	39,271	LH Fuel Pump	24,375	31-Dec-09	14,896	21,000	6,104
DT15	785-5	39,271	RH Fuel Pump	24,375	31-Dec-09	14,896	21,000	6,104

Dump Truck Component Hours at 28 February '19

Fleet #	Plant Model	Frame Hrs	Component	Last Overhaul Hrs	Last Overhaul Date	Current Comp Hours	Scheduled Hrs	Hours to Overhaul
DT15	785-5	39,271	Compressor (R)	322	04-Oct-13	38,949	21,000	-17,949
DT15	785-5	39,271	Compressor (F)	38,094	26-Jul-15	1,177	21,000	19,823
DT15	785-5	39,271	Water Pump	36,938	22-Dec-14	2,333	21,000	18,667
DT15	785-5	39,271	Radiator	33,239	27-Dec-12	6,032	21,000	14,968
DT15	785-5	39,271	Engine Damper	36,939	05-Jan-15	2,332	10,000	7,668
DT15	785-5	39,271	Transmission	25,806	28-May-10	13,465	14,000	535
DT15	785-5	39,271	Transmission Cooler	33,239	27-Dec-12	6,032	14,000	7,968
DT15	785-5	39,271	Transmission Pump	25,806	28-May-10	13,465	14,000	535
DT15	785-5	39,271	Differential	25,514	16-Jul-15	13,757	18,000	4,243
DT15	785-5	39,271	LH Final Drive	29,666	16-Jul-15	9,605	18,000	8,395
DT15	785-5	39,271	RH Final Drive	29,666	16-Jul-15	9,605	18,000	8,395
DT15	785-5	39,271	LHR Wheel Bgs (Pre-Load)	38,015	16-Jul-15	1,256	2,000	744
DT15	785-5	39,271	RHR Wheel Bgs (Pre-Load)	38,015	16-Jul-15	1,256	2,000	744
DT15	785-5	39,271	LHR Brakes	29,666	16-Jul-15	9,605	18,000	8,395
DT15	785-5	39,271	RHR Brakes	29,666	16-Jul-15	9,605	18,000	8,395
DT15	785-5	39,271	Brake Coolers	17,883	27-Jun-06	21,388	18,000	-3,388
DT15	785-5	39,271	LHR Strut	36,364	17-May-14	2,907	21,000	18,093
DT15	785-5	39,271	RHR Strut	38,084	23-Jul-15	1,187	21,000	19,813
DT15	785-5	39,271	LHF Strut	24,723	31-Dec-09	14,548	21,000	6,452
DT15	785-5	39,271	RHF Strut	13,600	15-Feb-05	25,671	21,000	-4,671
DT15	785-5	39,271	LHF Wheel Bearings	31,351	07-May-12	7,920	24,000	16,080
DT15	785-5	39,271	RHF Wheel Bearings	31,847	22-Jun-12	7,424	24,000	16,576
DT15	785-5	39,271	LHR Wheel Bearings	29,666	16-Jul-15	9,605	18,000	8,395
DT15	785-5	39,271	RHR Wheel Bearings	29,666	16-Jul-15	9,605	18,000	8,395
DT15	785-5	39,271	LHF Brakes	31,351	07-May-12	7,920	20,000	12,080
DT15	785-5	39,271	RHF Brakes	21,400	15-Jun-07	17,871	20,000	2,129
DT15	785-5	39,271	LH Steering Cylinder	33,162	18-Nov-12	6,109	21,000	14,891
DT15	785-5	39,271	RH Steering Cylinder	38,479	25-Apr-16	792	21,000	20,208
DT15	785-5	39,271	LH Hoist Cylinder	12,500	15-Oct-05	26,771	21,000	-5,771
DT15	785-5	39,271	LH Lower Hoist Cylinder Pin	37,460	18-Apr-15	1,811	24,000	22,189
DT15	785-5	39,271	RH Hoist Cylinder	12,500	15-Oct-05	26,771	21,000	-5,771
DT15	785-5	39,271	RH Lower Hoist Cylinder Pin	37,460	18-Apr-15	1,811	24,000	22,189
DT15	785-5	39,271	Hoist-Steering Pump	15,500	15-Sep-05	23,771	21,000	-2,771
DT15	785-5	39,271	Brake Cooling Pump	10,000	15-Jan-05	29,271	21,000	-8,271
DT15	785-5	39,271	Orbital Steering Valve	36,938	31-Dec-14	2,333	21,000	18,667
DT15	785-5	39,271	Operators Seat	34,792	14-Sep-13	4,479	10,000	5,521
DT15	785-5	39,271	Frame		15-Jun-99	39,271	40,000	729
DT15	785-5	Morowa						
DT18	785-5	39,290	Engine	17,500	15-Apr-06	21,790	21,000	-790
DT18	785-5	39,290	Injectors	17,500	15-Apr-06	21,790	21,000	-790
DT18	785-5	39,290	LH Turbo	37,791	03-Feb-15	1,499	21,000	19,501
DT18	785-5	39,290	RH Turbo	29,181	19-Oct-10	10,109	21,000	10,891
DT18	785-5	39,290	LH Fuel Pump	20,100	15-Oct-05	19,190	21,000	1,810
DT18	785-5	39,290	RH Fuel Pump	27,692	31-Oct-09	11,598	21,000	9,402
DT18	785-5	39,290	Compressor (R)	17,500	15-Apr-05	21,790	21,000	-790
DT18	785-5	39,290	Compressor (F)	17,500	15-Apr-05	21,790	21,000	-790
DT18	785-5	39,290	Water Pump	32,801	12-Nov-12	6,489	21,000	14,511
DT18	785-5	39,290	Radiator	39,003	04-Jul-15	287	21,000	20,713

Dump Truck Component Hours at 28 February '19

Fleet #	Plant Model	Frame Hrs	Component	Last Overhaul Hrs	Last Overhaul Date	Current Comp Hours	Scheduled Hrs	Hours to Overhaul
DT18	785-5	39,290	Engine Damper	31,953	05-May-12	7,337	10,000	2,663
DT18	785-5	39,290	Transmission	27,388	23-Apr-09	11,902	14,000	2,098
DT18	785-5	39,290	Transmission Cooler	39,003	04-Jul-15	287	14,000	13,713
DT18	785-5	39,290	Transmission Pump	27,388	23-Apr-09	11,902	14,000	2,098
DT18	785-5	39,290	Differential	35,760	27-Apr-14	3,530	18,000	14,470
DT18	785-5	39,290	LH Final Drive	17,013	06-Oct-14	22,277	18,000	-4,277
DT18	785-5	39,290	RH Final Drive	17,013	06-Oct-14	22,277	18,000	-4,277
DT18	785-5	39,290	LHR Wheel Bgs (Pre-Load)	37,029	06-Oct-14	2,261		
DT18	785-5	39,290	RHR Wheel Bgs (Pre-Load)	37,029	06-Oct-14	2,261		
DT18	785-5	39,290	LHR Brakes	37,029	06-Oct-14	2,261	18,000	15,739
DT18	785-5	39,290	RHR Brakes	37,029	06-Oct-14	2,261	18,000	15,739
DT18	785-5	39,290	Brake Coolers	22,885	15-Sep-06	16,405	18,000	1,595
DT18	785-5	39,290	LHR Strut	17,500	15-Apr-06	21,790	21,000	-790
DT18	785-5	39,290	RHR Strut	17,500	15-Apr-06	21,790	21,000	-790
DT18	785-5	39,290	LHF Strut	21,000	15-Jan-06	18,290	21,000	2,710
DT18	785-5	39,290	RHF Strut	17,500	15-Apr-05	21,790	21,000	-790
DT18	785-5	39,290	LHF Wheel Bearings	13,000	15-Dec-04	26,290	24,000	-2,290
DT18	785-5	39,290	RHF Wheel Bearings	13,000	15-Dec-04	26,290	24,000	-2,290
DT18	785-5	39,290	LHR Wheel Bearings	17,013	06-Oct-14	22,277	18,000	-4,277
DT18	785-5	39,290	RHR Wheel Bearings	17,013	06-Oct-14	22,277	18,000	-4,277
DT18	785-5	39,290	LHF Brakes	20,550	15-Dec-05	18,740	20,000	1,260
DT18	785-5	39,290	RHF Brakes	20,550	15-Dec-05	18,740	20,000	1,260
DT18	785-5	39,290	LH Steering Cylinder	12,975	07-Jul-12	26,315	21,000	-5,315
DT18	785-5	39,290	RH Steering Cylinder	38,454	01-May-15	836	21,000	20,164
DT18	785-5	39,290	LH Hoist Cylinder	39,290	19-May-17	0	21,000	21,000
DT18	785-5	39,290	LH Lower Hoist Cylinder Pin	35,099	05-Dec-13	4,191	24,000	19,809
DT18	785-5	39,290	RH Hoist Cylinder	25,397	12-Jul-08	13,893	21,000	7,107
DT18	785-5	39,290	RH Lower Hoist Cylinder Pin	35,099	05-Dec-13	4,191	24,000	19,809
DT18	785-5	39,290	Hoist-Steering Pump	30,532	23-Jun-11	8,758	21,000	12,242
DT18	785-5	39,290	Brake Cooling Pump	17,500	15-Jun-06	21,790	21,000	-790
DT18	785-5	39,290	Orbital Steering Valve	31,154	30-Dec-11	8,136	21,000	12,864
DT18	785-5	39,290	Operators Seat	39,246	31-Jul-15	44	10,000	9,956
DT18	785-5	39,290	Frame		15-Jun-99	39,290	40,000	710
DT18	785-5	Morowa						
DT24	785-5	43,575	Engine	33,012	16-Mar-12	10,563	21,000	10,438
DT24	785-5	43,575	Injectors	33,012	16-Mar-12	10,563	21,000	10,438
DT24	785-5	43,575	LH Turbo	42,503	07-Jan-15	1,072	21,000	19,929
DT24	785-5	43,575	RH Turbo	42,503	07-Jan-15	1,072	21,000	19,929
DT24	785-5	43,575	LH Fuel Pump	37,206	12-Mar-13	6,369	21,000	14,632
DT24	785-5	43,575	RH Fuel Pump	33,012	16-Mar-12	10,563	21,000	10,438
DT24	785-5	43,575	Compressor (R)	36,640	30-Jan-13	6,935	21,000	14,066
DT24	785-5	43,575	Compressor (F)	33,012	16-Mar-12	10,563	21,000	10,438
DT24	785-5	43,575	Water Pump	35,551	11-Sep-12	8,024	21,000	12,977
DT24	785-5	43,575	Radiator	33,012	16-Mar-12	10,563	21,000	10,438
DT24	785-5	43,575	Engine Damper	33,012	16-Mar-12	10,563	10,000	-563
DT24	785-5	43,575	Transmission	30,834	31-Jul-11	12,741	14,000	1,260
DT24	785-5	43,575	Transmission Cooler	33,012	16-Mar-12	10,563	14,000	3,438
DT24	785-5	43,575	Transmission Pump	30,834	31-Jul-11	12,741	14,000	1,260

Dump Truck Component Hours at 28 February '19

Fleet #	Plant Model	Frame Hrs	Component	Last Overhaul Hrs	Last Overhaul Date	Current Comp Hours	Scheduled Hrs	Hours to Overhaul
DT24	785-5	43,575	Differential	36,017	14-Nov-12	7,558	18,000	10,443
DT24	785-5	43,575	LH Final Drive	36,114	02-Dec-12	7,461	18,000	10,540
DT24	785-5	43,575	RH Final Drive	36,114	02-Dec-12	7,461	18,000	10,540
DT24	785-5	43,575	LHR Wheel Bgs (Pre-Load)	36,114	02-Dec-12	7,461		
DT24	785-5	43,575	RHR Wheel Bgs (Pre-Load)	36,114	02-Dec-12	7,461		
DT24	785-5	43,575	LHR Brakes	36,114	02-Dec-12	7,461	18,000	10,540
DT24	785-5	43,575	RHR Brakes	36,114	02-Dec-12	7,461	18,000	10,540
DT24	785-5	43,575	Brake Coolers	19,438	03-Oct-07	24,137	18,000	-6,137
DT24	785-5	43,575	LHR Strut	35,946	07-Oct-12	7,629	21,000	13,372
DT24	785-5	43,575	RHR Strut	30,254	05-May-11	13,321	21,000	7,680
DT24	785-5	43,575	LHF Strut	34,457	09-Jul-12	9,118	21,000	11,883
DT24	785-5	43,575	RHF Strut	24,175	26-Mar-10	19,400	21,000	1,601
DT24	785-5	43,575	LHF Wheel Bearings	35,579	15-Sep-12	7,996	24,000	16,005
DT24	785-5	43,575	RHF Wheel Bearings	35,579	15-Sep-12	7,996	24,000	16,005
DT24	785-5	43,575	LHR Wheel Bearings	36,114	02-Dec-12	7,461	18,000	10,540
DT24	785-5	43,575	RHR Wheel Bearings	36,114	02-Dec-12	7,461	18,000	10,540
DT24	785-5	43,575	LHF Brakes	17,000	01-May-07	26,575	20,000	-6,575
DT24	785-5	43,575	RHF Brakes	17,000	01-May-07	26,575	20,000	-6,575
DT24	785-5	43,575	LH Steering Cylinder	26,517	01-Jun-10	17,058	21,000	3,943
DT24	785-5	43,575	RH Steering Cylinder	26,517	01-Jun-10	17,058	21,000	3,943
DT24	785-5	43,575	LH Hoist Cylinder	32,620	15-Feb-12	10,955	21,000	10,046
DT24	785-5	43,575	LH Lower Hoist Cylinder Pin	33,647	19-May-12	9,928	24,000	14,073
DT24	785-5	43,575	RH Hoist Cylinder	38,086	27-Jun-13	5,489	21,000	15,512
DT24	785-5	43,575	RH Lower Hoist Cylinder Pin	38,086	27-Jun-13	5,489	24,000	18,512
DT24	785-5	43,575	Hoist-Steering Pump	25,028	31-Dec-09	18,547	21,000	2,454
DT24	785-5	43,575	Brake Cooling Pump	25,028	31-Dec-09	18,547	21,000	2,454
DT24	785-5	43,575	Orbital Steering Valve	29,683	19-Mar-11	13,892	21,000	7,109
DT24	785-5	43,575	Operators Seat	41,792	02-Nov-13	1,783	10,000	8,218
DT24	785-5	43,575	Frame		15-Jun-97	43,575	40,000	-3,575
DT24	785-5	Dalwallinu						
DT27	785-5	39,196	Engine	35,657	30-Nov-16	3,539	21,000	17,461
DT27	785-5	39,196	Injectors	35,657	30-Nov-16	3,539	21,000	17,461
DT27	785-5	39,196	LH Turbo	35,657	30-Nov-16	3,539	21,000	17,461
DT27	785-5	39,196	RH Turbo	35,657	30-Nov-16	3,539	21,000	17,461
DT27	785-5	39,196	LH Fuel Pump	35,657	30-Nov-16	3,539	21,000	17,461
DT27	785-5	39,196	RH Fuel Pump	35,657	30-Nov-16	3,539	21,000	17,461
DT27	785-5	39,196	Compressor (R)	35,657	30-Nov-16	3,539	21,000	17,461
DT27	785-5	39,196	Compressor (F)	35,744	21-Dec-16	3,452	21,000	17,548
DT27	785-5	39,196	Water Pump	35,657	30-Nov-16	3,539	21,000	17,461
DT27	785-5	39,196	Radiator	27,983	22-May-14	11,213	21,000	9,787
DT27	785-5	39,196	Engine Damper	38,976	10-Sep-18	220	10,000	9,780
DT27	785-5	39,196	Transmission	26,090	04-Nov-12	13,106	14,000	894
DT27	785-5	39,196	Transmission Cooler	27,983	22-May-14	11,213	14,000	2,787
DT27	785-5	39,196	Transmission Pump	26,090	04-Nov-12	13,106	14,000	894
DT27	785-5	39,196	Differential	32,622	05-Dec-15	6,574	18,000	11,426
DT27	785-5	39,196	LH Final Drive	30,889	09-Aug-15	8,307	18,000	9,693
DT27	785-5	39,196	RH Final Drive	30,889	09-Aug-15	8,307	18,000	9,693
DT27	785-5	39,196	LHR Wheel Bgs (Pre-Load)	30,889	09-Aug-15	8,307	2,000	-6,307

Dump Truck Component Hours at 28 February '19

Fleet #	Plant Model	Frame Hrs	Component	Last Overhaul Hrs	Last Overhaul Date	Current Comp Hours	Scheduled Hrs	Hours to Overhaul
DT27	785-5	39,196	RHR Wheel Bgs (Pre-Load)	30,889	09-Aug-15	8,307	2,000	-6,307
DT27	785-5	39,196	LHR Brakes	39,010	07-Oct-18	186	18,000	17,814
DT27	785-5	39,196	RHR Brakes	30,889	09-Aug-15	8,307	18,000	9,693
DT27	785-5	39,196	Brake Coolers		01-Sep-06	39,196	18,000	-21,196
DT27	785-5	39,196	LHR Strut		01-Sep-06	39,196	21,000	-18,196
DT27	785-5	39,196	RHR Strut		01-Sep-06	39,196	21,000	-18,196
DT27	785-5	39,196	LHF Strut	38,410	27-May-18	786	21,000	20,214
DT27	785-5	39,196	RHF Strut		01-Sep-06	39,196	21,000	-18,196
DT27	785-5	39,196	LHF Wheel Bearings	34,477	18-Apr-16	4,719	24,000	19,281
DT27	785-5	39,196	RHF Wheel Bearings	34,477	18-Apr-16	4,719	24,000	19,281
DT27	785-5	39,196	LHR Wheel Bearings	30,889	09-Aug-15	8,307	18,000	9,693
DT27	785-5	39,196	RHR Wheel Bearings	30,889	09-Aug-15	8,307	18,000	9,693
DT27	785-5	39,196	LHF Brakes	15,993	09-Feb-09	23,203	20,000	-3,203
DT27	785-5	39,196	RHF Brakes	15,993	09-Feb-09	23,203	20,000	-3,203
DT27	785-5	39,196	LH Steering Cylinder	37,787	21-Nov-17	1,409	21,000	19,591
DT27	785-5	39,196	RH Steering Cylinder	29,684	31-Mar-15	9,512	21,000	11,488
DT27	785-5	39,196	LH Hoist Cylinder		01-Sep-06	39,196	21,000	-18,196
DT27	785-5	39,196	LH Lower Hoist Cylinder Pin	29,473	09-Jan-15	9,723	24,000	14,277
DT27	785-5	39,196	RH Hoist Cylinder		01-Sep-06	39,196	21,000	-18,196
DT27	785-5	39,196	RH Lower Hoist Cylinder Pin	29,473	09-Jan-15	9,723	24,000	14,277
DT27	785-5	39,196	Hoist-Steering Pump	8,609	18-Jun-13	30,587	21,000	-9,587
DT27	785-5	39,196	Brake Cooling Pump		01-Sep-06	39,196	21,000	-18,196
DT27	785-5	39,196	Orbital Steering Valve	24,218	21-May-12	14,978	21,000	6,022
DT27	785-5	39,196	Operators Seat	38,973	25-Aug-18	223	10,000	9,777
DT27	785-5	39,196	Frame		01-Sep-06	39,196	40,000	804
DT27	785-5	Morowa						
DT28	785-5	42,441	Engine	37,190	10-May-16	5,251	21,000	15,749
DT28	785-5	42,441	Injectors	37,190	10-May-16	5,251	21,000	15,749
DT28	785-5	42,441	LH Turbo	37,190	10-May-16	5,251	21,000	15,749
DT28	785-5	42,441	RH Turbo	37,190	10-May-16	5,251	21,000	15,749
DT28	785-5	42,441	LH Fuel Pump	37,190	10-May-16	5,251	21,000	15,749
DT28	785-5	42,441	RH Fuel Pump	37,258	28-May-16	5,183	21,000	15,817
DT28	785-5	42,441	Compressor (R)	41,935	05-Aug-18	506	21,000	20,494
DT28	785-5	42,441	Compressor (F)	37,190	10-May-16	5,251	21,000	15,749
DT28	785-5	42,441	Water Pump	37,190	10-May-16	5,251	21,000	15,749
DT28	785-5	42,441	Radiator	35,355	05-Oct-15	7,086	21,000	13,914
DT28	785-5	42,441	Engine Damper	37,190	10-May-16	5,251	10,000	4,749
DT28	785-5	42,441	Transmission	31,849	27-Aug-14	10,592	14,000	3,408
DT28	785-5	42,441	Transmission Cooler	31,849	27-Aug-14	10,592	14,000	3,408
DT28	785-5	42,441	Transmission Pump	17,189	28-May-10	25,252	14,000	-11,252
DT28	785-5	42,441	Differential	29,016	09-Jun-13	13,425	18,000	4,575
DT28	785-5	42,441	LH Final Drive	29,016	09-Jun-13	13,425	18,000	4,575
DT28	785-5	42,441	RH Final Drive	36,505	08-Jan-16	5,936	18,000	12,064
DT28	785-5	42,441	LHR Wheel Bgs (Pre-Load)	38,431	11-Nov-16	4,010		
DT28	785-5	42,441	RHR Wheel Bgs (Pre-Load)	36,505	08-Jan-16	5,936		
DT28	785-5	42,441	LHR Brakes	38,431	11-Nov-16	4,010	18,000	13,990
DT28	785-5	42,441	RHR Brakes	36,505	08-Jan-16	5,936	18,000	12,064
DT28	785-5	42,441	Brake Coolers		01-Sep-06	42,441	18,000	-24,441

Dump Truck Component Hours at 28 February '19

Fleet #	Plant Model	Frame Hrs	Component	Last Overhaul Hrs	Last Overhaul Date	Current Comp Hours	Scheduled Hrs	Hours to Overhaul
DT28	785-5	42,441	LHR Strut		01-Sep-06	42,441	21,000	-21,441
DT28	785-5	42,441	RHR Strut	38,938	09-Jan-17	3,503	21,000	17,497
DT28	785-5	42,441	LHF Strut	40,646	30-Nov-17	1,795	21,000	19,205
DT28	785-5	42,441	RHF Strut	40,646	01-Dec-17	1,795	21,000	19,205
DT28	785-5	42,441	LHF Wheel Bearings	36,505	08-Jan-16	5,936	24,000	18,064
DT28	785-5	42,441	RHF Wheel Bearings	31,896	13-Oct-14	10,545	24,000	13,455
DT28	785-5	42,441	LHR Wheel Bearings	38,431	11-Nov-16	4,010	18,000	13,990
DT28	785-5	42,441	RHR Wheel Bearings	36,505	08-Jan-16	5,936	18,000	12,064
DT28	785-5	42,441	LHF Brakes	15,416	11-Feb-09	27,025	20,000	-7,025
DT28	785-5	42,441	RHF Brakes	15,416	11-Feb-09	27,025	20,000	-7,025
DT28	785-5	42,441	LH Steering Cylinder	40,649	14-Nov-17	1,792	21,000	19,208
DT28	785-5	42,441	RH Steering Cylinder	40,649	14-Nov-17	1,792	21,000	19,208
DT28	785-5	42,441	LH Hoist Cylinder	40,649	22-Nov-17	1,792	21,000	19,208
DT28	785-5	42,441	LH Lower Hoist Cylinder Pin	31,895	25-Sep-14	10,546	21,000	10,454
DT28	785-5	42,441	RH Hoist Cylinder		01-Sep-06	42,441	21,000	-21,441
DT28	785-5	42,441	RH Lower Hoist Cylinder Pin	31,895	25-Sep-14	10,546	21,000	10,454
DT28	785-5	42,441	Hoist-Steering Pump		01-Sep-06	42,441	21,000	-21,441
DT28	785-5	42,441	Brake Cooling Pump		01-Sep-06	42,441	21,000	-21,441
DT28	785-5	42,441	Orbital Steering Valve	31,640	21-Jul-14	10,801	21,000	10,199
DT28	785-5	42,441	Operators Seat	41,938	15-Aug-18	503	10,000	9,497
DT28	785-5	42,441	Frame		01-Sep-06	42,441	40,000	-2,441
DT28	785-5	Morowa						
DT34	785-5	38,603	Engine	29,150	07-Feb-13	9,453	21,000	11,547
DT34	785-5	38,603	Injectors	29,150	07-Feb-13	9,453	21,000	11,547
DT34	785-5	38,603	LH Turbo	29,150	07-Feb-13	9,453	21,000	11,547
DT34	785-5	38,603	RH Turbo	29,150	07-Feb-13	9,453	21,000	11,547
DT34	785-5	38,603	LH Fuel Pump	34,124	17-Jun-14	4,479	21,000	16,521
DT34	785-5	38,603	RH Fuel Pump	29,150	07-Feb-13	9,453	21,000	11,547
DT34	785-5	38,603	Compressor (R)	31,122	10-Oct-13	7,481	21,000	13,519
DT34	785-5	38,603	Compressor (F)	29,150	07-Feb-13	9,453	21,000	11,547
DT34	785-5	38,603	Water Pump	33,050	06-Mar-14	5,553	21,000	15,447
DT34	785-5	38,603	Radiator	28,029	02-Sep-12	10,574	21,000	10,426
DT34	785-5	38,603	Engine Damper	29,150	07-Feb-13	9,453	10,000	547
DT34	785-5	38,603	Transmission	24,985	16-Dec-11	13,618	14,000	382
DT34	785-5	38,603	Transmission Cooler	28,029	16-Dec-11	10,574	14,000	3,426
DT34	785-5	38,603	Transmission Pump	24,985	16-Dec-11	13,618	14,000	382
DT34	785-5	38,603	Differential	34,443	05-Aug-14	4,160	18,000	13,840
DT34	785-5	38,603	LH Final Drive	34,443	05-Aug-14	4,160	18,000	13,840
DT34	785-5	38,603	RH Final Drive	34,443	05-Aug-14	4,160	18,000	13,840
DT34	785-5	38,603	LHR Wheel Bgs (Pre-Load)	34,443	05-Aug-14	4,160		
DT34	785-5	38,603	RHR Wheel Bgs (Pre-Load)	34,443	05-Aug-14	4,160		
DT34	785-5	38,603	LHR Brakes	34,443	05-Aug-14	4,160	18,000	13,840
DT34	785-5	38,603	RHR Brakes	34,443	05-Aug-14	4,160	18,000	13,840
DT34	785-5	38,603	Brake Coolers	30,040	28-Apr-13	8,563	18,000	9,437
DT34	785-5	38,603	LHR Strut	33,782	14-May-14	4,821	21,000	16,179
DT34	785-5	38,603	RHR Strut	37,477	03-May-15	1,126	21,000	19,874
DT34	785-5	38,603	LHF Strut	37,876	01-Jun-15	727	21,000	20,273
DT34	785-5	38,603	RHF Strut	33,264	27-Mar-14	5,339	21,000	15,661

Dump Truck Component Hours at 28 February '19

Fleet #	Plant Model	Frame Hrs	Component	Last Overhaul Hrs	Last Overhaul Date	Current Comp Hours	Scheduled Hrs	Hours to Overhaul
DT34	785-5	38,603	LHF Wheel Bearings	28,590	31-Oct-12	10,013	24,000	13,987
DT34	785-5	38,603	RHF Wheel Bearings	28,590	31-Oct-12	10,013	24,000	13,987
DT34	785-5	38,603	LHR Wheel Bearings	34,443	05-Aug-14	4,160	18,000	13,840
DT34	785-5	38,603	RHR Wheel Bearings	34,443	05-Aug-14	4,160	18,000	13,840
DT34	785-5	38,603	LHF Brakes	10,000	01-Mar-08	28,603	20,000	-8,603
DT34	785-5	38,603	RHF Brakes	10,000	01-Mar-08	28,603	20,000	-8,603
DT34	785-5	38,603	LH Steering Cylinder	34,187	21-Jun-14	4,416	21,000	16,584
DT34	785-5	38,603	RH Steering Cylinder	29,637	12-Mar-13	8,966	21,000	12,034
DT34	785-5	38,603	LH Hoist Cylinder	38,598	21-May-18	5	21,000	20,995
DT34	785-5	38,603	LH Lower Hoist Cylinder Pin	34,280	07-Nov-93	4,323	24,000	19,677
DT34	785-5	38,603	RH Hoist Cylinder	38,233	02-Jul-15	370	21,000	20,630
DT34	785-5	38,603	RH Lower Hoist Cylinder Pin	34,280	07-Nov-93	4,323	24,000	19,677
DT34	785-5	38,603	Hoist-Steering Pump	33,071	11-Mar-14	5,532	21,000	15,468
DT34	785-5	38,603	Brake Cooling Pump		15-Jun-06	38,603	21,000	-17,603
DT34	785-5	38,603	Orbital Steering Valve	33,486	16-Apr-14	5,117	21,000	15,883
DT34	785-5	38,603	Operators Seat	24,941	24-Nov-11	13,662	10,000	-3,662
DT34	785-5	38,603	Frame		15-Jun-06	38,603	40,000	1,397
DT34	785-5	Morowa						
DT36	785-5	42,800	Engine	21,852	01-Jun-09	20,948	21,000	52
DT36	785-5	42,800	Injectors	21,852	01-Jun-09	20,948	21,000	52
DT36	785-5	42,800	LH Turbo	31,272	07-Oct-11	11,528	21,000	9,472
DT36	785-5	42,800	RH Turbo	33,852	14-Aug-12	8,948	21,000	12,052
DT36	785-5	42,800	LH Fuel Pump	21,852	01-Jun-09	20,948	21,000	52
DT36	785-5	42,800	RH Fuel Pump	21,852	01-Jun-09	20,948	21,000	52
DT36	785-5	42,800	Compressor (R)	29,626	10-May-11	13,174	21,000	7,826
DT36	785-5	42,800	Compressor (F)	21,852	01-Jun-09	20,948	21,000	52
DT36	785-5	42,800	Water Pump	37,876	10-Dec-13	4,924	21,000	16,076
DT36	785-5	42,800	Radiator	35,506	07-May-13	7,294	21,000	13,706
DT36	785-5	42,800	Engine Damper	36,878	30-Aug-13	5,922	10,000	4,078
DT36	785-5	42,800	Transmission	33,854	16-Oct-12	8,946	14,000	5,054
DT36	785-5	42,800	Transmission Cooler	35,506	07-May-13	7,294	14,000	6,706
DT36	785-5	42,800	Transmission Pump	33,854	16-Oct-12	8,946	14,000	5,054
DT36	785-5	42,800	Differential	32,254	12-Feb-12	10,546	18,000	7,454
DT36	785-5	42,800	LH Final Drive	26,875	08-Sep-10	15,925	18,000	2,075
DT36	785-5	42,800	RH Final Drive	26,875	08-Sep-10	15,925	18,000	2,075
DT36	785-5	42,800	LHR Wheel Bgs (Pre-Load)	31,924	23-Jan-12	10,876		
DT36	785-5	42,800	RHR Wheel Bgs (Pre-Load)	26,875	08-Sep-10	15,925		
DT36	785-5	42,800	LHR Brakes	26,875	08-Sep-10	15,925	18,000	2,075
DT36	785-5	42,800	RHR Brakes	26,875	08-Sep-10	15,925	18,000	2,075
DT36	785-5	42,800	Brake Coolers	26,875	08-Sep-10	15,925	18,000	2,075
DT36	785-5	42,800	LHR Strut	36,664	04-Aug-13	6,136	21,000	14,864
DT36	785-5	42,800	RHR Strut	36,664	04-Aug-13	6,136	21,000	14,864
DT36	785-5	42,800	LHF Strut	25,995	08-May-10	16,805	21,000	4,195
DT36	785-5	42,800	RHF Strut	41,728	18-Dec-14	1,072	21,000	19,928
DT36	785-5	42,800	LHF Wheel Bearings	34,537	05-Feb-13	8,263	24,000	15,737
DT36	785-5	42,800	RHF Wheel Bearings	34,537	05-Feb-13	8,263	24,000	15,737
DT36	785-5	42,800	LHR Wheel Bearings	26,875	08-Sep-10	15,925	18,000	2,075
DT36	785-5	42,800	RHR Wheel Bearings	26,875	08-Sep-10	15,925	18,000	2,075

Dump Truck Component Hours at 28 February '19

Fleet #	Plant Model	Frame Hrs	Component	Last Overhaul Hrs	Last Overhaul Date	Current Comp Hours	Scheduled Hrs	Hours to Overhaul
DT36	785-5	42,800	LHF Brakes	25,995	08-May-10	16,805	20,000	3,195
DT36	785-5	42,800	RHF Brakes		15-Jun-00	42,800	20,000	-22,800
DT36	785-5	42,800	LH Steering Cylinder	40,563	12-Sep-14	2,237	21,000	18,763
DT36	785-5	42,800	RH Steering Cylinder	26,770	10-Aug-10	16,030	21,000	4,970
DT36	785-5	42,800	LH Hoist Cylinder		15-Jun-00	42,800	21,000	-21,800
DT36	785-5	42,800	LH Lower Hoist Cylinder Pin	42,738	20-May-15	62	24,000	23,938
DT36	785-5	42,800	RH Hoist Cylinder		15-Jun-00	42,800	21,000	-21,800
DT36	785-5	42,800	RH Lower Hoist Cylinder Pin	42,738	20-May-15	62	24,000	23,938
DT36	785-5	42,800	Hoist-Steering Pump	29,389	23-Apr-11	13,411	21,000	7,589
DT36	785-5	42,800	Brake Cooling Pump		15-Jun-00	42,800	21,000	-21,800
DT36	785-5	42,800	Orbital Steering Valve	38,224	07-Jan-14	4,576	21,000	16,424
DT36	785-5	42,800	Operators Seat	38,848	24-Apr-14	3,952	10,000	6,048
DT36	785-5	42,800	Frame		15-Jun-00	42,800	40,000	-2,800
DT36	785-5	Dalwallinu						
DT39	785-5	35,237	Engine	21,435	13-Apr-12	13,802	21,000	7,199
DT39	785-5	35,237	Injectors	21,435	13-Apr-12	13,802	21,000	7,199
DT39	785-5	35,237	LH Turbo	29,834	15-Feb-16	5,403	21,000	15,598
DT39	785-5	35,237	RH Turbo	21,435	13-Apr-12	13,802	21,000	7,199
DT39	785-5	35,237	LH Fuel Pump	21,435	13-Apr-12	13,802	21,000	7,199
DT39	785-5	35,237	RH Fuel Pump	21,435	13-Apr-12	13,802	21,000	7,199
DT39	785-5	35,237	Compressor (R)	31,111	14-Jun-16	4,126	21,000	16,875
DT39	785-5	35,237	Compressor (F)	21,435	13-Apr-12	13,802	21,000	7,199
DT39	785-5	35,237	Water Pump	30,638	24-Apr-16	4,599	21,000	16,402
DT39	785-5	35,237	Radiator	24,138	02-Apr-14	11,099	21,000	9,902
DT39	785-5	35,237	Engine Damper	25,643	05-Nov-16	9,594	10,000	407
DT39	785-5	35,237	Transmission	26,056	12-Jan-15	9,181	14,000	4,820
DT39	785-5	35,237	Transmission Cooler	24,138	02-Apr-14	11,099	14,000	2,902
DT39	785-5	35,237	Transmission Pump	26,056	12-Jan-15	9,181	14,000	4,820
DT39	785-5	35,237	Differential	16,059	26-Mar-10	19,178	18,000	-1,178
DT39	785-5	35,237	LH Final Drive	20,688	16-Oct-11	14,549	18,000	3,452
DT39	785-5	35,237	RH Final Drive	27,670	16-May-15	7,567	18,000	10,434
DT39	785-5	35,237	LHR Brakes	20,688	16-Oct-11	14,549	18,000	3,452
DT39	785-5	35,237	RHR Brakes	27,670	16-May-15	7,567	18,000	10,434
DT39	785-5	35,237	Brake Coolers	20,688	16-Oct-11	14,549	18,000	3,452
DT39	785-5	35,237	LHR Strut		15-Jun-06	35,237	21,000	-14,237
DT39	785-5	35,237	RHR Strut		15-Jun-06	35,237	21,000	-14,237
DT39	785-5	35,237	LHF Strut	26,579	14-Feb-15	8,658	21,000	12,343
DT39	785-5	35,237	RHF Strut	26,926	10-Mar-15	8,311	21,000	12,690
DT39	785-5	35,237	LHF Wheel Bearings	25,391	18-Sep-14	9,846	24,000	14,155
DT39	785-5	35,237	RHF Wheel Bearings	24,541	23-Jun-14	10,696	24,000	13,305
DT39	785-5	35,237	LHR Wheel Bearings	20,688	16-Oct-11	14,549	18,000	3,452
DT39	785-5	35,237	RHR Wheel Bearings	27,670	16-May-15	7,567	18,000	10,434
DT39	785-5	35,237	LHF Brakes	8,022	15-Apr-08	27,215	20,000	-7,215
DT39	785-5	35,237	RHF Brakes	8,022	15-Apr-08	27,215	20,000	-7,215
DT39	785-5	35,237	LH Steering Cylinder	25,887	11-Dec-14	9,350	21,000	11,651
DT39	785-5	35,237	RH Steering Cylinder	33,102	01-Dec-17	2,135	21,000	18,866
DT39	785-5	35,237	LH Hoist Cylinder	31,250	10-Jul-16	3,987	21,000	17,014
DT39	785-5	35,237	LH Lower Hoist Cylinder Pin	22,805	07-Sep-13	12,432	24,000	11,569

Dump Truck Component Hours at 28 February '19

Fleet #	Plant Model	Frame Hrs	Component	Last Overhaul Hrs	Last Overhaul Date	Current Comp Hours	Scheduled Hrs	Hours to Overhaul
DT39	785-5	35,237	RH Hoist Cylinder		15-Jun-06	35,237	21,000	-14,237
DT39	785-5	35,237	RH Lower Hoist Cylinder Pin	22,805	07-Sep-13	12,432	24,000	11,569
DT39	785-5	35,237	Hoist-Steering Pump	16,010	17-Dec-09	19,227	21,000	1,774
DT39	785-5	35,237	Brake Cooling Pump	8,022	15-Apr-08	27,215	21,000	-6,215
DT39	785-5	35,237	Orbital Steering Valve	22,974	30-Sep-13	12,263	21,000	8,738
DT39	785-5	35,237	Operators Seat	32,574	19-Jan-17	2,663	10,000	7,338
DT39	785-5	35,237	Frame		15-Jun-06	35,237	40,000	4,764
DT39	785-5	Morowa						
DT42	785-5	43,346	Engine	31,667	10-Jun-15	11,679	21,000	9,321
DT42	785-5	43,346	Injectors	31,667	10-Jun-15	11,679	21,000	9,321
DT42	785-5	43,346	LH Turbo	33,517	16-Oct-15	9,829	21,000	11,171
DT42	785-5	43,346	RH Turbo	31,667	10-Jun-15	11,679	21,000	9,321
DT42	785-5	43,346	LH Fuel Pump	39,512	10-Nov-17	3,834	21,000	17,166
DT42	785-5	43,346	RH Fuel Pump	31,667	10-Jun-15	11,679	21,000	9,321
DT42	785-5	43,346	Compressor (R)	43,160	14-Dec-18	186	21,000	20,814
DT42	785-5	43,346	Compressor (F)	31,667	10-Jun-15	11,679	21,000	9,321
DT42	785-5	43,346	Water Pump	36,675	13-May-16	6,671	21,000	14,329
DT42	785-5	43,346	Radiator	30,843	03-Dec-14	12,503	21,000	8,497
DT42	785-5	43,346	Engine Damper	31,667	10-Jun-15	11,679	10,000	-1,679
DT42	785-5	43,346	Transmission	28,292	20-Feb-14	15,054	14,000	-1,054
DT42	785-5	43,346	Transmission Cooler	30,843	03-Dec-14	12,503	14,000	1,497
DT42	785-5	43,346	Transmission Pump	35,758	03-Mar-16	7,588	14,000	6,412
DT42	785-5	43,346	Differential	16,718	24-Jun-10	26,628	18,000	-8,628
DT42	785-5	43,346	LH Final Drive	33,023	14-Sep-15	10,323	18,000	7,677
DT42	785-5	43,346	RH Final Drive	33,023	14-Sep-15	10,323	18,000	7,677
DT42	785-5	43,346	LHR Wheel Bgs (Pre-Load)	33,023	14-Sep-15	10,323	2,000	-8,323
DT42	785-5	43,346	RHR Wheel Bgs (Pre-Load)	33,023	14-Sep-15	10,323	2,000	-8,323
DT42	785-5	43,346	LHR Brakes	33,023	14-Sep-15	10,323	18,000	7,677
DT42	785-5	43,346	RHR Brakes	33,023	14-Sep-15	10,323	18,000	7,677
DT42	785-5	43,346	Brake Coolers	16,718	24-Jun-10	26,628	18,000	-8,628
DT42	785-5	43,346	LHR Strut		15-Jun-06	43,346	21,000	-22,346
DT42	785-5	43,346	RHR Strut		15-Jun-06	43,346	21,000	-22,346
DT42	785-5	43,346	LHF Strut	28,643	24-Mar-14	14,703	21,000	6,297
DT42	785-5	43,346	RHF Strut	39,588	05-Nov-17	3,758	21,000	17,242
DT42	785-5	43,346	LHF Wheel Bearings	27,373	14-Nov-13	15,973	24,000	8,027
DT42	785-5	43,346	RHF Wheel Bearings	27,373	14-Nov-13	15,973	24,000	8,027
DT42	785-5	43,346	LHR Wheel Bearings	33,023	14-Sep-15	10,323	18,000	7,677
DT42	785-5	43,346	RHR Wheel Bearings	33,023	14-Sep-15	10,323	18,000	7,677
DT42	785-5	43,346	LHF Brakes	7,809	01-Mar-08	35,537	20,000	-15,537
DT42	785-5	43,346	RHF Brakes	7,809	01-Mar-08	35,537	20,000	-15,537
DT42	785-5	43,346	LH Steering Cylinder	39,514	30-Oct-17	3,832	21,000	17,168
DT42	785-5	43,346	RH Steering Cylinder	35,422	15-Feb-16	7,924	21,000	13,076
DT42	785-5	43,346	LH Hoist Cylinder	2,228	07-Aug-18	41,118	21,000	-20,118
DT42	785-5	43,346	LH Lower Hoist Cylinder Pin	31,315	27-Feb-15	12,031	24,000	11,969
DT42	785-5	43,346	RH Hoist Cylinder	26,391	22-May-13	16,955	21,000	4,045
DT42	785-5	43,346	RH Lower Hoist Cylinder Pin	31,315	27-Feb-15	12,031	24,000	11,969
DT42	785-5	43,346	Hoist-Steering Pump	11,471	01-Mar-09	31,875	21,000	-10,875
DT42	785-5	43,346	Brake Cooling Pump	11,471	01-Mar-09	31,875	21,000	-10,875

Dump Truck Component Hours at 28 February '19

Fleet #	Plant Model	Frame Hrs	Component	Last Overhaul Hrs	Last Overhaul Date	Current Comp Hours	Scheduled Hrs	Hours to Overhaul
DT42	785-5	43,346	Orbital Steering Valve	21,387	21-Oct-11	21,959	21,000	-959
DT42	785-5	43,346	Operators Seat	38,072	22-Oct-16	5,274	10,000	4,726
DT42	785-5	43,346	Frame		15-Jun-06	43,346	40,000	-3,346
DT42	785-5	Morowa						
DT43	785-5	38,269	Engine	20,765	22-Nov-11	17,504	21,000	3,497
DT43	785-5	38,269	Injectors	20,765	22-Nov-11	17,504	21,000	3,497
DT43	785-5	38,269	LH Turbo	20,765	22-Nov-11	17,504	21,000	3,497
DT43	785-5	38,269	RH Turbo	20,765	22-Nov-11	17,504	21,000	3,497
DT43	785-5	38,269	LH Fuel Pump	35,772	15-Nov-17	2,497	21,000	18,504
DT43	785-5	38,269	RH Fuel Pump	27,507	22-Jul-15	10,762	21,000	10,239
DT43	785-5	38,269	Compressor (R)	26,878	07-Sep-15	11,391	21,000	9,610
DT43	785-5	38,269	Compressor (F)	20,765	22-Nov-11	17,504	21,000	3,497
DT43	785-5	38,269	Water Pump	20,765	22-Nov-11	17,504	21,000	2
DT43	785-5	38,269	Radiator	26,664	22-Feb-15	11,605	21,000	9,396
DT43	785-5	38,269	Engine Damper	32,316	16-Jul-16	5,953	10,000	4,048
DT43	785-5	38,269	Transmission	31,417	08-Apr-16	6,852	14,000	7,149
DT43	785-5	38,269	Transmission Cooler	26,664	22-Feb-15	11,605	14,000	2,396
DT43	785-5	38,269	Transmission Pump	31,417	08-Apr-16	6,852	14,000	7,149
DT43	785-5	38,269	Differential	25,908	09-Nov-14	12,361	18,000	5,640
DT43	785-5	38,269	LH Final Drive	27,446	11-Jul-15	10,823	18,000	7,178
DT43	785-5	38,269	RH Final Drive	27,446	11-Jul-15	10,823	18,000	7,178
DT43	785-5	38,269	LHR Wheel Bgs (Pre-Load)	31,417	09-Apr-16	6,852	2,000	-4,852
DT43	785-5	38,269	RHR Wheel Bgs (Pre-Load)	31,417	09-Apr-16	6,852	2,000	-4,852
DT43	785-5	38,269	LHR Brakes	27,446	11-Jul-15	10,823	18,000	7,178
DT43	785-5	38,269	RHR Brakes	27,446	11-Jul-15	10,823	18,000	7,178
DT43	785-5	38,269	Brake Coolers	20,765	10-Dec-11	17,504	18,000	497
DT43	785-5	38,269	LHR Strut		15-Jun-06	38,269	21,000	-17,269
DT43	785-5	38,269	RHR Strut		15-Jun-06	38,269	21,000	-17,269
DT43	785-5	38,269	LHF Strut	35,259	20-Jun-17	3,010	21,000	17,991
DT43	785-5	38,269	RHF Strut	37,109	05-Jun-18	1,160	21,000	19,841
DT43	785-5	38,269	LHF Wheel Bearings	23,778	09-Mar-14	14,491	24,000	9,510
DT43	785-5	38,269	RHF Wheel Bearings	23,778	09-Mar-14	14,491	24,000	9,510
DT43	785-5	38,269	LHR Wheel Bearings	27,446	11-Jul-15	10,823	18,000	7,178
DT43	785-5	38,269	RHR Wheel Bearings	27,446	11-Jul-15	10,823	18,000	7,178
DT43	785-5	38,269	LHF Brakes	11,040	01-Dec-08	27,229	20,000	-7,229
DT43	785-5	38,269	RHF Brakes	11,040	01-Dec-08	27,229	20,000	-7,229
DT43	785-5	38,269	LH Steering Cylinder	32,584	14-Aug-16	5,685	21,000	15,316
DT43	785-5	38,269	RH Steering Cylinder	27,446	11-Jul-15	10,823	21,000	10,178
DT43	785-5	38,269	LH Hoist Cylinder		15-Jun-06	38,269	21,000	-17,269
DT43	785-5	38,269	LH Lower Hoist Cylinder Pin	26,348	29-Jan-15	11,921	24,000	12,080
DT43	785-5	38,269	RH Hoist Cylinder		15-Jun-06	38,269	21,000	-17,269
DT43	785-5	38,269	RH Lower Hoist Cylinder Pin	26,348	29-Jan-15	11,921	24,000	12,080
DT43	785-5	38,269	Hoist-Steering Pump	35,772	25-Nov-17	2,497	21,000	18,504
DT43	785-5	38,269	Brake Cooling Pump	11,040	01-Dec-08	27,229	21,000	-6,229
DT43	785-5	38,269	Orbital Steering Valve	9,675	01-Jun-08	28,594	21,000	-7,594
DT43	785-5	38,269	Operators Seat	35,772	15-Nov-17	2,497	10,000	7,504
DT43	785-5	38,269	Frame		15-Jun-06	38,269	40,000	1,732
DT43	785-5	Morowa						

Dump Truck Component Hours at 28 February '19

Fleet #	Plant Model	Frame Hrs	Component	Last Overhaul Hrs	Last Overhaul Date	Current Comp Hours	Scheduled Hrs	Hours to Overhaul
DT44	785-5	42,092	Engine	28,986	26-Jul-16	13,106	21,000	7,895
DT44	785-5	42,092	Injectors	28,986	26-Jul-16	13,106	21,000	7,895
DT44	785-5	42,092	LH Turbo	39,992	12-Apr-16	2,100	21,000	18,901
DT44	785-5	42,092	RH Turbo	28,986	26-Jul-16	13,106	21,000	7,895
DT44	785-5	42,092	LH Fuel Pump	40,361	26-Jun-16	1,731	21,000	19,270
DT44	785-5	42,092	RH Fuel Pump	40,361	26-Jun-16	1,731	21,000	19,270
DT44	785-5	42,092	Compressor (R)	28,986	26-Jul-16	13,106	21,000	7,895
DT44	785-5	42,092	Compressor (F)	28,986	26-Jul-16	13,106	21,000	7,895
DT44	785-5	42,092	Water Pump	28,986	26-Jul-16	13,106	21,000	7,895
DT44	785-5	42,092	Radiator	38,367	06-Dec-15	3,725	21,000	17,276
DT44	785-5	42,092	Engine Damper	41,093	11-Oct-16	999	10,000	9,002
DT44	785-5	42,092	Transmission	26,528	04-Aug-13	15,564	14,000	-1,564
DT44	785-5	42,092	Transmission Cooler	26,528	04-Aug-13	15,564	14,000	-1,564
DT44	785-5	42,092	Transmission Pump	26,528	04-Aug-13	15,564	14,000	-1,564
DT44	785-5	42,092	Differential	24,854	17-Sep-12	17,238	18,000	763
DT44	785-5	42,092	LH Final Drive	40,197	18-May-16	1,895	18,000	16,106
DT44	785-5	42,092	RH Final Drive	40,197	18-May-16	1,895	18,000	16,106
DT44	785-5	42,092	LHR Wheel Bgs (Pre-Load)	40,197	18-May-16	1,895		
DT44	785-5	42,092	RHR Wheel Bgs (Pre-Load)	40,197	18-May-16	1,895		
DT44	785-5	42,092	LHR Brakes	40,197	18-May-16	1,895	18,000	16,106
DT44	785-5	42,092	RHR Brakes	40,197	18-May-16	1,895	18,000	16,106
DT44	785-5	42,092	Brake Coolers	20,935	20-Jul-11	21,157	18,000	-3,157
DT44	785-5	42,092	LHR Strut	2,045	15-Oct-06	40,047	21,000	-19,047
DT44	785-5	42,092	RHR Strut	17,253	30-Apr-10	24,839	21,000	-3,839
DT44	785-5	42,092	LHF Strut	30,853	03-Jun-14	11,239	21,000	9,762
DT44	785-5	42,092	RHF Strut	32,368	18-Sep-14	9,724	21,000	11,277
DT44	785-5	42,092	LHF Wheel Bearings	41,376	23-Nov-16	716	24,000	23,285
DT44	785-5	42,092	RHF Wheel Bearings	29,665	20-Mar-14	12,427	24,000	11,574
DT44	785-5	42,092	LHR Wheel Bearings	40,197	18-May-16	1,895	18,000	16,106
DT44	785-5	42,092	RHR Wheel Bearings	40,197	18-May-16	1,895	18,000	16,106
DT44	785-5	42,092	LHF Brakes	8,304	01-Dec-07	33,788	20,000	-13,788
DT44	785-5	42,092	RHF Brakes	8,304	01-Dec-07	33,788	20,000	-13,788
DT44	785-5	42,092	LH Steering Cylinder	28,068	07-Dec-13	14,024	21,000	6,977
DT44	785-5	42,092	RH Steering Cylinder	22,372	10-Mar-12	19,720	21,000	1,281
DT44	785-5	42,092	LH Hoist Cylinder	40,669	21-Aug-16	1,423	21,000	19,578
DT44	785-5	42,092	LH Lower Hoist Cylinder Pin	34,723	11-Mar-15	7,369	24,000	16,632
DT44	785-5	42,092	RH Hoist Cylinder	10,712	01-Sep-08	31,380	21,000	-10,380
DT44	785-5	42,092	RH Lower Hoist Cylinder Pin	34,723	11-Mar-15	7,369	24,000	16,632
DT44	785-5	42,092	Hoist-Steering Pump	42,092	11-Apr-17	-1	21,000	21,001
DT44	785-5	42,092	Brake Cooling Pump	8,304	01-Dec-07	33,788	21,000	-12,788
DT44	785-5	42,092	Orbital Steering Valve	22,372	10-Mar-12	19,720	21,000	1,281
DT44	785-5	42,092	Operators Seat	40,196	20-May-16	1,896	10,000	8,105
DT44	785-5	42,092	Frame		15-Jun-06	42,092	40,000	-2,092
DT44	785-5	Morowa						
DT106	B40D	12,540	Engine		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	Engine Water Pump		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	Fuel Injector		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	Fuel Pump		15-Aug-08	12,540	16,000	3,460

Dump Truck Component Hours at 28 February '19

Fleet #	Plant Model	Frame Hrs	Component	Last Overhaul Hrs	Last Overhaul Date	Current Comp Hours	Scheduled Hrs	Hours to Overhaul
DT106	B40D	12,540	Turbocharger		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	Radiator Assembly		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	Torque Convertor		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	Transmission		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	Drop Box	11,733	30-Apr-18	807	16,000	15,193
DT106	B40D	12,540	Transmission Cooler	8,847	23-Dec-16	3,693	16,000	12,307
DT106	B40D	12,540	Cylinder Hoist LH		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	Cylinder Hoist RH		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	Cylinder Steering LH		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	Cylinder Steering RH		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	Hydraulic Motor		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	Hydraulic Pump Main		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	Fan Motor		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	Hydraulic Cooler Fan		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	Hydraulic Oil Cooler		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	Front Differential		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	Centre Differential		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	Rear Differential		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	Pos 1 Brakes LHF		15-Aug-08	12,540	24,000	11,460
DT106	B40D	12,540	Pos 2 Brakes RHF		15-Aug-08	12,540	24,000	11,460
DT106	B40D	12,540	Pos 3 Brakes LHC		15-Aug-08	12,540	24,000	11,460
DT106	B40D	12,540	Pos 4 Brakes RHC		15-Aug-08	12,540	24,000	11,460
DT106	B40D	12,540	Pos 4 Brakes RHC		15-Aug-08	12,540	24,000	11,460
DT106	B40D	12,540	Pos 5 Brakes LHR		15-Aug-08	12,540	24,000	11,460
DT106	B40D	12,540	Pos 1 Final drive LHF		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	Pos 2 Final drive RHF		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	Pos 3 Final drive LHC		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	Pos 4 Final drive RHC		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	Pos 5 Final drive LHR		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	Pos 6 Final drive RHR		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	LHF Strut		15-Aug-08	12,540	16,000	3,460
DT106	B40D	12,540	RHF Strut	11,880	06-Jul-18	660	16,000	15,340
DT106	B40D	12,540	Suspension Assembly LHR		15-Aug-08	12,540	24,000	11,460
DT106	B40D	12,540	Suspension Assembly RHR		15-Aug-08	12,540	24,000	11,460
DT106	B40D	12,540	Operators Seat	7,194	31-Oct-15	5,346	10,000	4,654
DT106	B40D	12,540	Frame		15-Aug-08	12,540	30,000	17,460
DT106	B40D	Northam						
DT107	B40D	15,180	Engine		15-May-08	15,180	16,000	820
DT107	B40D	15,180	Engine Water Pump		15-May-08	15,180	16,000	820
DT107	B40D	15,180	Fuel Injector		15-May-08	15,180	16,000	820
DT107	B40D	15,180	Fuel Pump		15-May-08	15,180	16,000	820
DT107	B40D	15,180	Turbocharger	14,651	23-May-18	529	16,000	15,471
DT107	B40D	15,180	Radiator Assembly		15-May-08	15,180	16,000	820
DT107	B40D	15,180	Torque Convertor	10,927	10-Sep-16	4,253	16,000	11,747
DT107	B40D	15,180	Transmission		15-May-08	15,180	16,000	820
DT107	B40D	15,180	Drop Box		15-May-08	15,180	16,000	820
DT107	B40D	15,180	Transmission Cooler	10,911	08-Sep-16	4,269	16,000	11,731
DT107	B40D	15,180	Cylinder Hoist LH		15-May-08	15,180	16,000	820

Dump Truck Component Hours at 28 February '19

Fleet #	Plant Model	Frame Hrs	Component	Last Overhaul Hrs	Last Overhaul Date	Current Comp Hours	Scheduled Hrs	Hours to Overhaul
DT107	B40D	15,180	Cylinder Hoist RH		15-May-08	15,180	16,000	820
DT107	B40D	15,180	Cylinder Steering LH	9,758	04-Aug-15	5,422	16,000	10,578
DT107	B40D	15,180	Cylinder Steering RH	10,006	08-Sep-15	5,174	16,000	10,826
DT107	B40D	15,180	Hydraulic Motor		15-May-08	15,180	16,000	820
DT107	B40D	15,180	Hydraulic Pump Main	9,455	11-Mar-15	5,725	16,000	10,275
DT107	B40D	15,180	Fan Motor		15-May-08	15,180	16,000	820
DT107	B40D	15,180	Hydraulic Cooler Fan		15-May-08	15,180	16,000	820
DT107	B40D	15,180	Hydraulic Oil Cooler	8,905	24-Jan-15	6,275	16,000	9,725
DT107	B40D	15,180	Front Differential		15-May-08	15,180	16,000	820
DT107	B40D	15,180	Centre Differential		15-May-08	15,180	16,000	820
DT107	B40D	15,180	Rear Differential		15-May-08	15,180	16,000	820
DT107	B40D	15,180	Pos 1 Brakes LHF		15-May-08	15,180	24,000	8,820
DT107	B40D	15,180	Pos 2 Brakes RHF		15-May-08	15,180	24,000	8,820
DT107	B40D	15,180	Pos 3 Brakes LHC		15-May-08	15,180	24,000	8,820
DT107	B40D	15,180	Pos 4 Brakes RHC		15-May-08	15,180	24,000	8,820
DT107	B40D	15,180	Pos 4 Brakes RHC		15-May-08	15,180	24,000	8,820
DT107	B40D	15,180	Pos 5 Brakes LHR		15-May-08	15,180	24,000	8,820
DT107	B40D	15,180	Pos 1 Final drive LHF		15-May-08	15,180	16,000	820
DT107	B40D	15,180	Pos 2 Final drive RHF		15-May-08	15,180	16,000	820
DT107	B40D	15,180	Pos 3 Final drive LHC		15-May-08	15,180	16,000	820
DT107	B40D	15,180	Pos 4 Final drive RHC		15-May-08	15,180	16,000	820
DT107	B40D	15,180	Pos 5 Final drive LHR		15-May-08	15,180	16,000	820
DT107	B40D	15,180	Pos 6 Final drive RHR		15-May-08	15,180	16,000	820
DT107	B40D	15,180	LHF Strut		15-May-08	15,180	16,000	820
DT107	B40D	15,180	RHF Strut		15-May-08	15,180	16,000	820
DT107	B40D	15,180	Suspension Assembly LHR		15-May-08	15,180	24,000	8,820
DT107	B40D	15,180	Suspension Assembly RHR		15-May-08	15,180	24,000	8,820
DT107	B40D	15,180	Operators Seat	10,380	05-Jun-16	4,800	10,000	5,200
DT107	B40D	15,180	Frame		15-May-08	15,180	30,000	14,820
DT107	B40D	Northam						
DT108	B40D	12,748	Engine		15-Sep-08	12,748	16,000	3,252
DT108	B40D	12,748	Engine Water Pump	8,484	15-Jan-17	4,264	16,000	11,736
DT108	B40D	12,748	Fuel Injector		15-Sep-08	12,748	16,000	3,252
DT108	B40D	12,748	Fuel Pump		15-Sep-08	12,748	16,000	3,252
DT108	B40D	12,748	Turbocharger	12,208	02-Aug-18	540	16,000	15,460
DT108	B40D	12,748	Radiator Assembly		15-Sep-08	12,748	16,000	3,252
DT108	B40D	12,748	Torque Convertor		15-Sep-08	12,748	16,000	3,252
DT108	B40D	12,748	Transmission		15-Sep-08	12,748	16,000	3,252
DT108	B40D	12,748	Drop Box		15-Sep-08	12,748	16,000	3,252
DT108	B40D	12,748	Transmission Cooler	7,682	20-Oct-16	5,066	16,000	10,934
DT108	B40D	12,748	Cylinder Hoist LH		15-Sep-08	12,748	16,000	3,252
DT108	B40D	12,748	Cylinder Hoist RH		15-Sep-08	12,748	16,000	3,252
DT108	B40D	12,748	Cylinder Steering LH		15-Sep-08	12,748	16,000	3,252
DT108	B40D	12,748	Cylinder Steering RH		15-Sep-08	12,748	16,000	3,252
DT108	B40D	12,748	Hydraulic Motor		15-Sep-08	12,748	16,000	3,252
DT108	B40D	12,748	Hydraulic Pump Main	7,825	19-Nov-16	4,923	16,000	11,077
DT108	B40D	12,748	Fan Motor		15-Sep-08	12,748	16,000	3,252
DT108	B40D	12,748	Hydraulic Cooler Fan		15-Sep-08	12,748	16,000	3,252

Dump Truck Component Hours at 28 February '19

Fleet #	Plant Model	Frame Hrs	Component	Last Overhaul Hrs	Last Overhaul Date	Current Comp Hours	Scheduled Hrs	Hours to Overhaul
DT108	B40D	12,748	Hydraulic Oil Cooler		15-Sep-08	12,748	16,000	3,252
DT108	B40D	12,748	Front Differential	4,557	15-Jun-13	8,191	16,000	7,809
DT108	B40D	12,748	Centre Differential		15-Sep-08	12,748	16,000	3,252
DT108	B40D	12,748	Rear Differential		15-Sep-08	12,748	16,000	3,252
DT108	B40D	12,748	Pos 1 Brakes LHF		15-Sep-08	12,748	24,000	11,252
DT108	B40D	12,748	Pos 2 Brakes RHF		15-Sep-08	12,748	24,000	11,252
DT108	B40D	12,748	Pos 3 Brakes LHC		15-Sep-08	12,748	24,000	11,252
DT108	B40D	12,748	Pos 4 Brakes RHC		15-Sep-08	12,748	24,000	11,252
DT108	B40D	12,748	Pos 4 Brakes RHC		15-Sep-08	12,748	24,000	11,252
DT108	B40D	12,748	Pos 5 Brakes LHR		15-Sep-08	12,748	24,000	11,252
DT108	B40D	12,748	Pos 1 Final drive LHF		15-Sep-08	12,748	16,000	3,252
DT108	B40D	12,748	Pos 2 Final drive RHF		15-Sep-08	12,748	16,000	3,252
DT108	B40D	12,748	Pos 3 Final drive LHC		15-Sep-08	12,748	16,000	3,252
DT108	B40D	12,748	Pos 4 Final drive RHC		15-Sep-08	12,748	16,000	3,252
DT108	B40D	12,748	Pos 5 Final drive LHR		15-Sep-08	12,748	16,000	3,252
DT108	B40D	12,748	Pos 6 Final drive RHR		15-Sep-08	12,748	16,000	3,252
DT108	B40D	12,748	LHF Strut		15-Sep-08	12,748	16,000	3,252
DT108	B40D	12,748	RHF Strut	5,350	30-Mar-14	7,398	16,000	8,602
DT108	B40D	12,748	Suspension Assembly LHR		15-Sep-08	12,748	24,000	11,252
DT108	B40D	12,748	Suspension Assembly RHR		15-Sep-08	12,748	24,000	11,252
DT108	B40D	12,748	Operators Seat	10,936	03-Nov-17	1,812	10,000	8,188
DT108	B40D	12,748	Frame		15-Sep-08	12,748	30,000	17,252
DT108	B40D	Division St						
DT109	B40D	15,684	Engine	12,228	09-Sep-16	3,456	16,000	12,544
DT109	B40D	15,684	Engine Water Pump	12,228	09-Sep-16	3,456	16,000	12,544
DT109	B40D	15,684	Fuel Injector	12,228	09-Sep-16	3,456	16,000	12,544
DT109	B40D	15,684	Fuel Pump	12,228	09-Sep-16	3,456	16,000	12,544
DT109	B40D	15,684	Turbocharger	12,228	09-Sep-16	3,456	16,000	12,544
DT109	B40D	15,684	Radiator Assembly		15-Jun-08	15,684	16,000	316
DT109	B40D	15,684	Torque Convertor		15-Jun-08	15,684	16,000	316
DT109	B40D	15,684	Transmission		15-Jun-08	15,684	16,000	316
DT109	B40D	15,684	Transmission Cooler	10,949	06-Jul-15	4,735	16,000	11,265
DT109	B40D	15,684	Cylinder Hoist LH	10,817	07-Jun-15	4,867	16,000	11,133
DT109	B40D	15,684	Cylinder Hoist RH	14,505	05-Aug-17	1,179	16,000	14,821
DT109	B40D	15,684	Cylinder Steering LH		15-Jun-08	15,684	16,000	316
DT109	B40D	15,684	Cylinder Steering RH	11,484	19-Oct-15	4,200	16,000	11,800
DT109	B40D	15,684	Hydraulic Motor		15-Jun-08	15,684	16,000	316
DT109	B40D	15,684	Hydraulic Pump Main	14,505	29-Jul-17	1,179	16,000	14,821
DT109	B40D	15,684	Fan Motor		15-Jun-08	15,684	16,000	316
DT109	B40D	15,684	Hydraulic Cooler Fan		15-Jun-08	15,684	16,000	316
DT109	B40D	15,684	Hydraulic Oil Cooler		15-Jun-08	15,684	16,000	316
DT109	B40D	15,684	Front Differential		15-Jun-08	15,684	16,000	316
DT109	B40D	15,684	Centre Differential		15-Jun-08	15,684	16,000	316
DT109	B40D	15,684	Rear Differential		15-Jun-08	15,684	16,000	316
DT109	B40D	15,684	Pos 1 Brakes LHF		15-Jun-08	15,684	24,000	8,316
DT109	B40D	15,684	Pos 2 Brakes RHF		15-Jun-08	15,684	24,000	8,316
DT109	B40D	15,684	Pos 3 Brakes LHC		15-Jun-08	15,684	24,000	8,316
DT109	B40D	15,684	Pos 4 Brakes RHC		15-Jun-08	15,684	24,000	8,316

Dump Truck Component Hours at 28 February '19

Fleet #	Plant Model	Frame Hrs	Component	Last Overhaul Hrs	Last Overhaul Date	Current Comp Hours	Scheduled Hrs	Hours to Overhaul
DT109	B40D	15,684	Pos 4 Brakes RHC		15-Jun-08	15,684	24,000	8,316
DT109	B40D	15,684	Pos 5 Brakes LHR		15-Jun-08	15,684	24,000	8,316
DT109	B40D	15,684	Pos 1 Final drive LHF		15-Jun-08	15,684	16,000	316
DT109	B40D	15,684	Pos 2 Final drive RHF		15-Jun-08	15,684	16,000	316
DT109	B40D	15,684	Pos 3 Final drive LHC		15-Jun-08	15,684	16,000	316
DT109	B40D	15,684	Pos 4 Final drive RHC		15-Jun-08	15,684	16,000	316
DT109	B40D	15,684	Pos 5 Final drive LHR		15-Jun-08	15,684	16,000	316
DT109	B40D	15,684	Pos 6 Final drive RHR		15-Jun-08	15,684	16,000	316
DT109	B40D	15,684	LHF Strut		15-Jun-08	15,684	16,000	316
DT109	B40D	15,684	RHF Strut	14,757	23-Apr-18	927	16,000	15,073
DT109	B40D	15,684	Suspension Assembly LHR		15-Jun-08	15,684	24,000	8,316
DT109	B40D	15,684	Suspension Assembly RHR		15-Jun-08	15,684	24,000	8,316
DT109	B40D	15,684	Operators Seat	8,312	13-Nov-14	7,372	10,000	2,628
DT109	B40D	15,684	Frame		15-Jun-08	15,684	30,000	14,316
DT109	B40D	Division St						